

APPROVAL OF SERVICE SUPPLIERS

This is to certify that

Maritime Radio Co.

Ulsan, Republic of Korea

is granted acceptance for

Inspection and testing of radio communication equipment and AIS in accordance with the GL Rules for Classification and the Surveys and Procedural Requirements for Service Suppliers providing Services for Vessels classed with DNV GL.

This service supplier certificate will be accepted for use with all rule sets published by DNV GL.

This Certificate is valid until **2019-04-10**.

Issued at **Ulsan** on **2016-03-10**



for **DNV GL**

This document has been digitally signed and
will therefore not have handwritten signatures

Han, Yong Kun

**Ulsan CMC/FIS Coordinator, Principal
surveyor**

This Certificate may be withdrawn if:

1. The service provided has been improperly carried out or the results improperly reported.
2. The surveyor has found any deficiencies in the accepted operating systems of the service supplier.
3. The firm has failed to inform of any major changes having effect on the quality of the service rendered.
4. The conditions listed in the certificate are changed and/or are not fulfilled.

APPROVAL OF SERVICE SUPPLIERS

This is to certify that

Maritime Radio Co.

Ulsan, Republic of Korea

is granted acceptance for

Annual Survey and Testing of Voyage Data Recorders on Ships, High Speed and Light Craft and Mobile Offshore Units, classed by the Society, in accordance with Approval Programme No. 412 and IACS UR Z17, as amended.

This service supplier certificate will be accepted for use with all rule sets published by DNV GL. **See the following page(s) for details regarding application.**

This Certificate is valid until **2019-04-09**.

Issued at **Ulsan** on **2016-03-10**



for **DNV GL**

This document has been digitally signed and will therefore not have handwritten signatures

Han, Yong Kun

Ulsan CMC/FIS Coordinator, Principal surveyor

This Certificate may be withdrawn if:

1. The service provided has been improperly carried out or the results improperly reported.
2. The surveyor has found any deficiencies in the accepted operating systems of the service supplier.
3. The firm has failed to inform of any major changes having effect on the quality of the service rendered.
4. The conditions listed in the certificate are changed and/or are not fulfilled.